


**AERIAL** 

**152 CHARLES STREET** 

BALANCE BA ARCHITECTS





**AERIAL** 


**152 CHARLES STREET** 


BALANCE
ARCHITECTS






















"LANDED FROM OUTER SPACE"

"HORRIBLE"

"ROOF DECKS AREN'T ACTUALLY USED"

"SNORKEL TO THE ROOF"

"CRAMPED ENTRANCE"

"NO CONTINUITY OR RELATIONSHIP BETWEEN BUILDINGS"





- REMOVED ROOF DECK FROM EXISTING BUILDING
- SIMILAR FENESTRATION RHYTHM, DIFFERENT FENESTRATION TYPE
- SNORKEL IS A DORMER
- CARRIED ACROSS SIDE YARD ROOF LINES BETWEEN BUILDINGS
- REAR ROOF DECK ORIENT AWAY FROM 158 CHARLES MORE PRIVACY
- FENCE BETWEEN 152 & 158 CHARLES

- UNIT 2 ENTRANCE MOVED TO REAR
- UNIT 2 FOOT PRINT SIMPLIFIED (REMOVED JOGS)
- UNIT 1 DEDICATED OUTDOOR AREA
- MOVED STAIRS AWAY FROM WINDOWS







March 20, 2021

- PUNCHED WINDOWS CASEMENT
- LIMITED TRIM/ORNAMENTATION
- SIMPLIFIED GEOMETRY


UNIT 2 PRECEDENT

152 CHARLES STREET









**PERSPECTIVE** 

152 CHARLES STREET

BALANCE ARCHITECTS





PERSPECTIVE

152 CHARLES STREET

BALANCE ARCHITECTS








PERSPECTIVE


152 CHARLES STREET

BALANCE ARCHITECTS










**EQUINOX 9 AM** 




SOLSTICE 9 AM




EQUINOX 12 PM



SOLSTICE 12 PM



**EQUINOX 4 PM** 



SOLSTICE 4 PM



